Medford Service Center; Road Crew Building
1319 East McAndrews Road (Bldg. #2301)
Medford
Jackson County
Oregon

HABS ORE 15-MED

PHOTOGRAPHS

Historic American Buildings Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107

HABS ORE 15-MED, 1B-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

Medford Service Center, Road Crew Building (Building #2301) HABS No. OR-160-B 1319 McAndrews Road Medford Jackson County Oregon

| Natalie Brown | , Photographer April 1993 |
|---------------|---|
| OR-160-B-1 | VIEW OF NORTH SIDE AND WEST FRONT OF ROAD CREW BUILDING (BUILDING #2301) SHOWING OFFICE AREA IN NEAR SECTION, FACING SOUTHEAST. |
| OR-160-B-2 | VIEW OF WEST FRONT AND SOUTH SIDE OF BUILDING #2301, FACING NORTHEAST. |
| OR-160-B-3 | VIEW OF INTERIOR OF BUILDING #2301, FACING WEST. |
| OR-160-B-4 | VIEW OF INTERIOR OF BUILDING #2301, FACING EAST. |

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.